

# DEPARTMENT OF EDUCATION

---

**Paul Givan, Minister**  
Rathgael House, Balloo Road  
Bangor, BT19 7PR

---

**Timothy Gaston MLA**  
**Parliament Buildings**  
**Ballymiscaw**  
**Stormont**

26 February 2025  
AQW 22401/22-27

Timothy Gaston MLA has asked:

To ask the Minister of Education to detail the damage to school estates by Storm Éowyn, including an estimate of the cost for the completion of repairs.

ANSWER

Details of the damage reported to the Education Authority (EA) and the Department of Education following Storm Éowyn is set out in a table which I have deposited in the Assembly Library.

The EA has advised that the cost for completion of repairs is currently estimated at £2.7 million.



**Paul Givan MLA**  
**Minister of Education**

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Abbey Community College	Roof leak in between room 22 and 23. (flat roof) 2 panes of glass smashed in assembly hall - very high - single glazed window - metal windows
Abbey Primary	Passenger lift hasn't worked since the storm - possible fuse or electrical issue
Abercorn Primary School	Reported several trees down between school boundary and adjacent property taking power lines down also.
Academy Primary	Damage to Nursery School roof.
Aghadrumsee Primary	2 panels broken on outdoor learning area. 2 panels on security fence to be replaced
All Children's Primary	Pitched roof leaking in the P3 Classroom
All Saints	<b>JUNIOR</b> - Make safe/replace flashing on flat roof at front of building - Wood is exposed. <b>SENIOR</b> - Replace skylight in changing room - has blown off, changing room is exposed
All Saints Primary	Roof leak in assembly hall - pitched roof -water coming in through wooden ceiling. Slates off in different places around school - large section of metal guttering hanging down. PV panel
Ampertaine Primary School	The intruder alarm cannot be reset since the storm leaving the school unprotected.
Andrews Memorial Primary	Iron gates at the front of the school have shifted in the storm and one gate will not close -too heavy to lift back into place, leaving the school open after hours/
Annalong Primary School	2 missing roof tiles at the front of the school - pitched roof .2 roof tiles off at P4 this is a separate building. 2 pieces of soffit to be refitted at the P3 area.
Antrim Primary School	Flat roof has blown off the Mobile Classroom 1 Glass skylight broken in the Infant toilets 1 Plastic Dome skylight broken in the Infant toilet Electrics affected by roof leaks in classroom. Damaged bin compound at entrance

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Ardnashee School	<p><b>LOWER</b> - Ridge and roof tiles off in various areas of the school.</p> <p><b>UPPER</b> - Carry out site clearance and temporary roofing works due to storm damage</p> <p>Investigate and repair electrical cables that have fallen and become damaged by the storm</p> <p>Loose Decra sheeting to classroom</p> <p>Flat repair of area above "old" multi-purpose room in the language unit</p> <p>Access hatch, believed to be off 2 storey flat roof between the pitched roofs of the main buildings</p> <p>Loose Decra sheeting to mobile classroom</p> <p>Make watertight the felt pitched roof of the 4 way (primary) mobile adjacent to the reception building</p> <p>Detached gutter</p> <p>Replace approx 15ft of fascia above the main entrance door on the two-storey block of the language unit, facing the reception building. Decorate to match adjoining.</p> <p>Replace 1 roof tile and 1 ridge tile at old Caretaker's house</p>
Armagh Christian Brothers' Primary School	<p>Wooden fencing around nursery is damaged</p> <p>Stone wall at front of school has collapsed and fallen out onto the Keady Road footpath</p> <p>2 panes of glass damaged - 1 in P1 classroom and 1 in girls' toilet (both bottom block)</p>
Armoy Primary School	Roof leak at corridor area before the fourth skylight - bucket underneath.
Armstrong Primary School	<p>Roof tiles missing need replaced at the Office end and lead flashing to be replaced Ridge tiles to be replaced at the Principals Office</p> <p>Replace glass in the skylight in the roof space above the P6HG</p> <p>Tree uprooted north end of the playground - leaning at 45%. H&amp;S risk it could fall onto footpath to observatory</p>
Arvalee School and Resource Centre	Door opener
Ashfield Boys' High School	Repair 2 large fencing panels on the football pitch which have come down during the storm (Metal mesh fencing)
Ashgrove Primary School	<p>Please evaluate and repair Gas cover box blown off at P6 mobile area and needs replaced. Repair damage to ICT mobile hut roof. Wooden slat fence has blown down in turning circle area.</p> <p>Replace Side plastic panel of roof that has blown off at kitchen area.</p>
Assumption Grammar School	<p>Number of trees down blocking access to steps down to bus park.</p> <p>Railings down the steps have also been damaged but until trees are cleared, railings can't be assessed.</p> <p>Loose cables</p> <p>Leak in roof</p>
Augher Central Primary School	Minor roof repairs.
Aughnacloy High School	Roof Repairs 1 felt roof is damaged in the Art/Gym/HE department 1 no tile roof damaged in the Music Mobile

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Ballinamallard Primary	Outside light in the ground cover has come off and wires exposed. Cone put over to cover. Outside lights need checked. Fascia board blown off the corner of P3 classroom
Ballougry Primary	Investigate report from neighbour that part of the roof has blown off the Mobile Classroom. Carry out an appraisal of the M & E installation for the mobile classroom.
Ballycastle High School	1 PVC window in boys gym has been damaged with the storm - High level.
Ballyclare High School	1 single glazed, metal framed window has been smashed on the 3rd floor Private Study area Pitched roof in technology end (starts as a pitched goes into a flat and then up to a pitch again) has lost several tiles and edging of both pitched ends 3rd floor languages building in Languages area 6ft tear in felt roof which is causing significant leaks in numerous locations along main corridor and staffroom.
Ballyclare Primary School	Roof leak in old school building, tiles/ridge tiles missing and there is hole in the roof 6" round where slate is missing. 2 trees have fallen and damaged ibex fencing panels.
Ballyclare Secondary School	Fallen trees, part obstructing Avondale Road. Mobile 2 door blown open. Lock not working 1 Steel cabinet at the front of Mobile 3 has lost the door.
Ballycraig Primary School	Please repair PVC cladding to tank house. Remove fallen tree from playground.
Ballycraig PS MK	Repair leaking dome skylight in washroom and carry out consequential repairs to ceiling due to water ingress*ceiling is about to come down and would require to be made safe asap.
Ballyhenry Primary School	2.5m of fascia blown off in storm and polystyrene balls in classroom. Electric Roller Shutter at the main entrance will not open and close properly. Main front door of school.
Ballyholland Primary School	Several roof slates missing.
Ballymacash Primary	Roof tiles missing in several locations and flashing, tree needs inspecting as partially down. Tiles that are missing in courtyard area is causing a leak into resource area.
Ballymacricket Primary	40m guttering at back of school come off Both (2) gas boilers have stopped firing (do have hot water) electric going to panel etc but no pilot light firing.
Ballymacricket Primary SMK	No heat or hot water - gas heating - one boiler not firing.
Ballymacward Primary	Wooden fence has blown down at side of the school - P1/P2/P3 play area. Pitched roof leak outside P4 classroom

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Ballymagee Primary	Tiles off the roof in nursery unit. Classroom store water is coming in through as there is damage to the roof (possible lead flashing has been blown off.
Ballymagee Youth Wing	Led flashing on the roof has been damaged by the storm.
Ballymena Primary School	Approx. 30 slates have blown off 2-storey pitched roof at rear of building - tiles have blown off, section of play-ground has been cordoned off for H&S.
Ballymoney Model Integrated Primary School	Fallen tree blocking car turning route for ease of access. Loose down pipes and guttering at the front of the school and loose downpipes at the back of the school outside the sports hall.
Ballynahinch Central Meals SMK	12 tiles down - kitchen roof.
Ballynahinch High School	Approx 25 ridge tiles of roof plus slates broken 2 fallen trees on site - 1 of the trees is at a tilt and is leaning against another and is in danger of falling into neighbouring land one is located behind the kitchen area.
Ballysillan Primary	A piece of felt and fascia board have blown and hanging at P1 flat roof.
Ballytober Primary School	1 panel of fence is down at front of the building
Ballyvester Primary	Slates missing needs replace on the Main Building - Front and back
Banbridge Academy	20 ridge tiles off and a few slates off the roof at the back of the Math's Department. Spouting at Science department has come loose.
Banbridge High School	Sports hall ridge tile off and boiler house ridge tile lifted at one side and a roof tile off the boys changing room area - also a lid off on extraction unit in same area.
Bangor Central Integrated Primary	Roof leak in assembly hall - pitched roof.
Bangor Grammar School	Substantial damage to roofs
Belleek Primary	Fallen trees reported on school grounds.
Belmont Primary School	Repair fascia that has pulled away in two areas, two panels in each (4) - Outside main entrance and other outside room 6 ladder height - single storey.
Bethlehem Nursery	Loose roof tiles need secured at the school - pitched roof. Wooden playhouse has shifted to the left off the blocks that it sits on to keep it off the ground.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Birches Primary School	3 roof tiles and 4 slates have come away after storm (corner p6 classroom & roof outside p2 play-area) H&S - slates still at the edge of roof. Lights and Boiler not working following NIE power being restored. Felt to be repaired on the flat roof of the garage
Blackmountain Primary	Electric shutters that covers the front door at nursery area as they have come off runner.
Blessed Trinity College	<b>ANTRIM ROAD SITE</b> - Part of the Flat roof has metal edging, and it is ready to fall down on the Playing Field. Part of the Flat Roof at G Block has blown off <b>SOMERTON ROAD SITE</b> - Make safe & repair metal flashing on flat felt roof above geography entrance - has partially detached and is overhanging at the door. Building Supervisor will cordon area
Bligh's Lane Nursery	Make safe flat roof felt covering above the Nursery building.
Bloomfield Collegiate	Flat felt roof leak in Curran Building - causing heavy water ingress in office.2. Several dislodged ridge tiles on pitched roofs on both the Gray Building
Bloomfield Road Primary	Large hole to be repaired on the pitched roof in the Dining Hall - 6ft wide - Aluminium panels
Bloomfield Road Primary SMK	Extractor fan blown off roof.
Bocombra Primary School	Large 40ft conifer tree has fallen chipper needed - trunking and branches strewn everywhere. Also, in same area a lot of trees have uprooted. Pvc cladding at front, rear, boiler house, area above assembly hall area and another area above library. NK type fence - (Ibex) fencing in the corner at the back wall has been ripped off and needs new brackets to reattach the fence to the posts. Perspex curved roof panels blown off the bike shed needing replaced. The two panels at the sides are ok but the curved ones are gone.
Braidside Integrated Primary School	Broken fencing due to fallen trees from adjacent premises
Breda Academy	6 Roof tiles loose need reattached and repaired near the pathway and exits doors - ( 3 Storey high) 7 large trees on the school property are damaged and in a dangerous position. 2-3 of them have toppled and the rest are leaning on other trees.
Broadbridge Primary	Dislodged ridge tiles at rear of building at infant block - area has been cordoned off for H&S.
Bronte Primary School	1 roof tile is off assembly hall - high level pitched roof
Brookfield Special	Streetlight broken and needs to be replaced after being hit by a shed roof. 2 wooden shed roofs blown off and have blown into the streetlight in carpark.
Brooklands Primary	Roof tiles have come off the canteen and some loose Soffit at the front entrance has come away. Nursery building - Remove large tree branch which has fallen into the nursery garden.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Bunscoil an Traonaigh	Plastic covering is loose and not secure at outside covered play area at the nursery unit. Replace cover that is over the gas tap urgently as gas tap is now exposed.
Bunscoil an tSleibhe Dhuibh Primary	Lead flashing on the Nursery unit has been damaged by the Storm
Bunscoil Bheann Mhadagain Primary	Damage to pitched roof - a section of fascia has detached at left-hand side of front entrance; several tiles have dislodged/are damaged from the Cliftonville Rd. side of building;
Bunscoil Cholmcille Primary	Repairs to the main front vehicle entrance gates. A) Replace 1 damaged Paladin fence pale to gate cladding. B) Straighten 1 vertical.
Bunscoil Phobal Feirste	Nursery fence damaged.
Bushvalley Primary School	Roof tiles missing at following locations: 1 Ridge tile missing above the Hall, roof tiles above the P4 Room, 1 roof tile above the Junior toilets, 1 roof tile above the P2 classroom.
Bushvalley PS MK	Casing on the extractor fan is loose needs secured at the side of the building
Cairnshill Primary	Ridge tile blown off P3 block.
Camphill Primary School	3 Roof soffit panels above high level window (8Ft x 2Ft - metal) they have come loose on one side. 6 ridge infills need fixed.
Carnalridge Primary School	6 tiles of the pitched roof at the back of the school. 1 tile is hanging loose so the playground has been cordoned off. All lead flashing on the skylight has come off.
Carniny Primary School	External timber fire exit door in outside mobile area was caught in wind - not fully closing now.
Carrick Primary School (Lurgan)	Drain spout at front of school - the bracket has fallen off and spout is hanging
Carrickfergus Academy	<b>JUNIOR SITE</b> - 2 skylights off the girls changing room changing room number 1 and female staff toilet. 5 panes of glass broken in the greenhouse and need replaced and also the door of the greenhouse is damaged and hanging off. Several trees fallen with one fallen onto power line Sports hall roof pouring in water. Metal trim/fascia has come loose allowing water inside of walls. <b>SENIOR SITE</b> - Broken pane of glass - old steel frame single pane, located top north, very high up. will need scaffolding/ ladder.
Carrickfergus Grammar School	2 dugouts at hockey pitch uprooted and 2 Perspex sheets removed and referee's dugout badly damaged.
Carrickfergus Model Primary School	Guttering damaged in storm - high up on roof. MEWP required Several sections of mobile classroom roofs damaged. Clear drain located beside canteen - drain is blocked with debris from the storm. Concerned it will cause sinks in the SMK to back up.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Carrowdore Primary	Above the switch room part of the roof has come away and water is seeping in.
Carrowdore Primary SMK	Extractor fan has been damaged in the storm and the lid has gone and water is dripping in.
Carryduff Primary	large tree down - rear of school 12 ft long
Castle Tower School	Lightning wire has come away from the roof at the Nursery area Flood lights that have moved in the storm and need realigned Large tree down at the post 16 mobile has taken part of the fence and is out over the pedestrian foot path. Damage to aluminium roof at the Nursery end.
Castledawson Primary School	Fallen tree obstructing main entrance to school, Spouting and Downpipe broken off outside exit door in Assembly Hall causing water to come down at doorway. Doorway is used daily.
Castlederg High	Part of the Wire sheeting fence blown down in the wind 1 aluminium sheet has blown off the roof at the youth wing and the rest of the flashing is flapping in the wind
Castlederg High SMK	Flat roof leaking in the Dining
Castlereagh AEP Centre	At rear of mobile large section of roofing ripped off and wooden framing exposed. Substantial rain has got in. Internal walls and carpets soaked. Dehumidifier required
Castlereagh Nursery	Make safe & repair 4 green mesh metal fence panels at rear of nursery - panels were damaged by an uprooted tree which has now been removed.
Castleroe Primary School	2 roof tiles to be replaced at the front of the school & Plastic guttering to be repaired at the front of the school
Cavehill Primary	Lead flashing needs secured to the flat roof beside the solar panel. 6 Roof tiles need replaced at the solar panel.
Cedar Integrated Primary School	No damage to premises but number of trees down
Cedar Lodge SS	Roof tiles plus ridge tiles off the primary school roof - part of school closed off - Roof tiles off in Secondary school - roof exposed
Christ The King Primary	Guttering has come down outside the P6 area.
Churchill Primary School	Replace / repair approx. 3 slate tiles on pitched roof - 2 storey
City of Armagh High School	Replace missing roof tiles in maths department area, assembly hall and French department (pitched roof). Repair skylight on flat roof above room 128 - aluminium frame and Perspex cover detached Cut back boundary trees at football pitch to reduce their height as they're leaning towards adjacent houses. Tree surgeons attended and advised school to log this.
Clandeboy Primary	1 Security light not working in the Playground area
Clarawood Special	Perimeter fence has been damaged by a fallen tree.



**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Clare Primary SMK	Rain cover off the flu pipe of the oil burner
Clea Primary School	Roof tiles missing in several locations.
Cliftonville Integrated Primary School	Repair vertical barrier at front driveway - has partially detached and is bent at a right angle. Pitched roof leak above Assembly Hall - approx. 7 old tiles have blown off and are broken and also 3 old tiles to be replaced at the back school building - playground area
Clonalig Primary School	Roof tiles on corner of main roof missing. Pitched tile roof above P4 classroom. - Replace Perspex on Canopy outside Modular building (Metal frame with Perspex)
Clonalig Primary School MK	Damage Facia over the office and toilet came off outside. Several roof slates that have come off as result of storm damage.
Clough Primary School	3 metres of wooden fencing behind the P7 mobile has blown over. Roof - Felt on the Nursery shed has blown off and lifted - needs re- secured. The piece of felt should be okay to be put back on again. 2 ridge tiles - front left of the main entrance have come off with the storm. 2 ridge tiles off the Assembly Hall. Fire escape door into the Assembly Hall has been pulled of the hinge at the bottom - Needs secured to prevent access.
Clough PS MK	Cover/replace skylight on flat roof above School Meals Kitchen (SMK)
Cloughoge Primary School	3 Roof tiles need replaced at the front of the building 2 Roof tiles need replaced at the back corner of the building Pitched roof leaks in the corridor area Remove fallen tree at the back of school and repair damaged steel fence.
Clounagh Junior High School	Large area of felt roof over HE classrooms. Cast iron rainwater goods need checked in several locations and there are also 6 trees fallen within school site.
Colaiste Feirste	4 wooden fence panels to be repaired at the Bin shed Plastic guttering and down spouts to be repaired/replaced at the Mobile Classrooms
Coleraine College	Butyl edging has lifting all around the Gym roof , needs re-secured. (new roof)
Coleraine College Central MK	Badly damaged roof over the kitchen hall approx. 260m sq. (currently butyl / PVC & 40mm insulation) Remove damaged roof covering and saturated insulation. Replace with 120mm Insulation.
Coleraine Grammar School	Roof/window damage and damage to trees
Comber Primary	Remove 3 large trees blown down in playground. Unblock sewer drain in playground (playground flooded), drain cover sealed shut unable to open. Missing ridge tile on assembly hall roof.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Convent Of Mercy Nursery	One large single pane is broken in Classroom 2 2 down pipes have been damaged - both at front of school relace broken clips and refit downpipes. Timber fencing has come away from support poles in outdoor enclosure area. Tiles lifted at eaves and at verge. Perspex panel off the canopy and missing outside room 2. Replace panel and trims and check all sheeting to the canopy.
Cookstown High School	Repair wooden fencing at Chemistry. Replace/Replace High level guttering at the Sports Hall on Block 3 Investigate and repair flat roof in block one - all the rubber has come off and is lying on the ground - this a 2 sto-rey roof. Heras' site fencing blown over by the recent storm
Cookstown High SMK	Wooden fence round bin yard has come down
Cookstown Nursery School	Damage to wire metal fencing and steel posts in playground area.
Corran Integrated Primary School	Ridge tiles damaged/lost Damaged fence Solar panel dislodged - disrupting supply of hot water
Cortamlet Primary School	1 curved Perspex in canopy destroyed in storm from P6/7 mobile.
Craigavon Senior High School (Portadown)	H&S - Metal cladding has blown off and needs replaced at the top of the Drama Room 3 panes broken on the Gym roof
Creggan Primary School	Loose tiles at front of school - several appear to be dislodged and are at risk of falling above main entrance. Caller requested for front roof area to be assessed. Fencing at oil tank enclosure at side of school - wooden frame is loose.
Cross and Passion College	Damage to Sports Hall roof. Streetlight broken in main car park damaged - live wires exposed. Damage to timber fire exit door and frame to Technology Workshop. Has been temporarily secured but not functioning as a fire exit door.
Cross and Passion College MK	broken glass in window at dishwasher area (single) and glazing has blown off the window at dining area.
Crumlin Integrated College	window blown in at a support room Fascia panels broken on sports hall roof - high level roof. Perspex window in LSC broken and wooden frame bent - Window in staffroom requires new hinges. A large tree rooted in residence next door to school is about to fall. If it does fall it will fall on power lines attached to the school including the kitchen.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Culcrow Primary School	Flat lead roof above main school office - section of lead has detached and other sections are starting to lift, concerned it will cause a leak in the office as timber is exposed.
Cumran Primary	Down pipes at year 3, 6 and 7 spouting needs inserted back into brackets and resecured.
Currie Primary	Slates off at the rear of the school, water leaking in ISC room and outreach 2 room at front of school
D H Christie Memorial Primary School	Flat roof leak over girls' toilet. Felt has come away in the storm. Flat Roof leak in senior corridor. P5 Girls Toilets - plasterboard ceiling fallen in.
Dalriada School	Damage to Home Economics Roof Roof repairs Tree removal Re-socket of rugby post Fence repairs
Damhead Primary School	Wooden fence is down between school and residential home next door Panel blown off sign at assembly hall
Darkley Primary School	Ridge tiles missing and roof tiles need replaced around the building also a large hole needs repaired above the P1 toilet area
Dean Maguirc High	CCTV
Deanby Centre - former Our Lady's PS	Pitched roof leak in P1 classroom area, seems to be coming in above window also , unsure of exact source but think main cause is the roof.
Derryboye Primary	3 slates of the pitched roof at the edge. Canopy over the Mobile door has blown off.
Derrychrin Primary School	4 Roof tiles missing need replaced on the pitched roof at the P1 Classroom. 1 Roof tile missing needs replace on the opposite side of the P1 Classroom. 1 Roof tile missing needs replaced.
Derrygonnelly Primary	Roof tiles loose and missing need replaced on the pitched roof Fire exit door off the hinges and needs repaired at the Mobile Classroom
Dominican College	Large window damaged - currently being repaired. Emergency doors damaged but repairable. Smaller windows damaged. Minor leaks
Donacloney Primary School	10ft strip of soffit board is loose and needs re-secured above P6
Donaghadee Primary School	Section of cement-coated cladding on exterior wall of room 3/ICT suite - has detached completely from part of wall between ground floor and second floor. Front gates damaged in storm can't be closed Loose roof tiles at high level above entrance doors in dangerous condition to be made safe to allow school opening. Also roof damaged to Nursery.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Donard Special School	Felt roof on a garden shed at the senior playground 8ft by 8ft sheet of Perspex needs replaced on an outside canopy at the junior playground - blown off completely and sheet is damaged - may need replaced Also wooden fence needs repaired.
Down High School	Replacement 2 sets of rugby posts and ground sockets to match existing Wooden fence between T27 and ~T28 has blown down attend and repair fence. Roof leak in T 28 mobile - flat mineral felt roof. Flat roof leak at Art department - high level - 3 story roof - section of felt has blown back and drip bar is hanging down H&S issue. Roof at U1 to U 4 has approx 50 slates off - fibre cement slates possible acm.
Downshire Nursery School	Since power cut at the school after the storm damage - the electric roller shutter at the front door of the school is not operating.
Downshire Primary School	skylight has significant damage from winds P7 area high level double story building also a few slates down.
Dromara Primary	Several tiles off the pitched roofs around the school
Dromore Central Primary School	Fence down at back playground. Two lengths of panel down near a water feature. Loose slate sitting in gutter at front elevation. Close all open window sashes in the building. Replace boarding to 2nr rear first floor windows in the newer wing.
Dromore High School	Roof tiles off from the Assembly Hall pitched roof - Wood Panelling around mobile 55 has been blown off gutters damaged at rear of the school.6 roof tiles off gym. Roof in 6th form toilet leaking
Dromore Road Primary School	Roof tiles sitting loose above both entrance doors to the school.4 tiles at the front door.3 tiles at the playground.
Drumachose Primary	Repair / replace damaged window which has blown in at the boiler house. Double glazed glass needs replaced.
Drumahoe Primary	In the AST centre disabled toilet - ceiling fan is faulty - making a strange noise and not turning - possible ingress of debris from the recent storm.
Drumlins Integrated Primary School	3 downpipes detached Missing soffits Damage to external play equipment storage
Drumnamoe Nursery School	Replace approx 14 ridge tiles which have come off 4 different areas of the building. (pitched roof).
Drumrane Primary School	Part of the roof has blown off over the assembly hall. M & E installation in the vicinity of the assembly hall and the partial loss of the roof
Dunclug College	Damage to felt on low pitched roof above both canteens
Dunclug Primary School	Repair felt on flat roof where two water tanks are located

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Dundonald High School	12 roof tiles off in D Block. Approx 12 roof tiles off in D Block 6. Approx 2 tiles and 1 ridge tile off in Block B17. Repair damaged galvanised fence on perimeter of school between C and D blocks The electric doors at the front of the school are not closing properly, possibly due to water getting in during the storm.
Dundonald Primary	Roof Mounted Fan has blown off roof during storm. Perimeter trees have fallen in several locations. Rear playground, right of carpark, left of school into neighbours and left of entrance.
Dundonald Primary SMK	specialist contractor to attend and replace roof ventilation cowl on SMK
Dunluce School	Repair 3 flat roof leaks, teaching block link corridor, music room and Room T8 store area. Skylight has blown off in Art room corridor - flat roof - Temp covered for now with tarp Repair / replace damaged plastic fascia board that has blown off at science block and teaching block areas Repair flat trocal roof leaks in the following areas: salon, nurture room, and planning room 1 - buckets underneath.2. Clear blocked outlet on flat roof of girls' changing room.
Dunmurry Primary	Set of double wooden gates at front of school - gates have completely detached, caller says they're beyond repair. Gates were attached to built-in metal wall brackets. Ridge tiles blown off P4 cloakroom single storey roof - 10 Approx. - Access possible off flat roof.
Dunseverick Primary School	Leak in ceiling in P5/6 Classroom close to light fitting. Plasterboard ceiling. Pitch roof.
Earlview Primary School	Please evaluate and repair 1 radiator in the principal's office not heating, 1 radiator not heating in the main. Timber outdoor learning shelter - Felt has been stripped off the plywood roof. Supply & fit new grey black roofing felt over timber plywood roofing - Roof structure is ok Gate has been damaged that leads to the pond, Urgent as it is a health and safety issue. may need 2 new post and boards.
Eden Primary School Carrickfergus	A wooden door has come off the water tank area at rear car park. Also, a wooden gate broken and off hinge at infant playground and a small section of fascia.
Edenderry Nursery	Electric shutter on access to playground area from classroom. The cover at top, is hanging onto the ground and area cannot be used Repair metal railings surrounding perimeter wall Clear/ jet blocked storm drain located near bin store.
Edenderry Primary School (Banbridge)	2 metal fence panels damaged in the storm at the side of L1.
Edenderry Primary School (Portadown)	Shed at the back of the school where the doors have blown off - doors are off and locks and frames will need repaired.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Edendork Primary School	10 tiles off the pitched roof and others loose and there is felt lying in the yard. Remove 3 trees which have fallen in the play area
Edmund Rice College	Main gates off hinges - H&S
Edwards Primary	broken Perspex sheet over nursery covered area.
Eglinton Primary	Every board broken from wall in storm above P7 classroom and rubber element which sits where the door closes needs glued down above store in dining hall
Enniskillen Model Primary	Down pipe has come away from the guttering on top level roof, damaged to low level zinc roof at courtyard.
Enniskillen Nursery	Rear of school - 12 ft tree is down and lying on the fence adjacent to car park. 1 green wire fence was damaged due to a fallen tree during the storm, 2 panels damaged and bent
Enniskillen Royal Grammar School	<b>Lough Shore site</b> - ridge tiles, slates and lead flashing dislocated. <b>Cooper Crescent site</b> -felt blown off flat roof resulting in water damage to the classrooms below.
Erne Integrated College	windows in Technology have cracked plus the gutters in back of school have come off plus the down pipes have also come down.
Euston Street Primary	Fence post pillar is wobbling around. Approx 6 tiles off around building / pitched roof single storey. Fence post pillar is wobbling around needs concreted back in
Fairview Primary School	Severe roof leak in foyer Repair fault with 4 security cameras Fault with external access control side door and rear door - will not operate One section of fencing broken at front part of playground. Part of the gazebo has blown off at rear of school.
Fane Street Primary	Perimeter wall to school collapsed needs making safe.
Faughanvale Primary	Top floor corridor and throughout classrooms 5 and 7 cracks are present in plasterboard, pitched felted roof.
Fivemiletown Primary School	Various locations of missing roof slates. A few missing roof tiles and lead from bell tower.
Fleming Fulton Special	Various trees and branches down all over site and blocking pathways and a tree has fell on children's play area. Chimney pots and slates have come off old Victorian building at front of site - pitched roof Flat Felt roof above technology room is peeling back (coming away from edge). No water ingress now.
Florencecourt Primary SMK	Roof tiles have lifted and cracked on the pitched roof on the kitchen
Foley Primary School	Replace/refix Dekra roof tiles on mobile - approx. 50% have blown off Cables which have come off the flat roof and are a hazard to pupils in the playground.
Forge Integrated Primary	Tree is hanging over school and private resident. Needs to be cut down so it doesn't damage fence.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Fort Hill College	Internal storm drain - backed up and now leaking through the ceiling - middle of Room 19 - not affecting any electrics at present - close to a light fitting - approx. 2 foot away.
Forth River Primary	Repair pitched roof of building – 2 ridge tiles are dislodged, 2 sections of guttering have detached, and a section of fascia has detached.
Fountain Primary	S&F approx 4 replacement roof tiles to the front of the school on the 2 storey Assembly Hall roof. Pitched roof leak above the P3/4 Classroom. Investigate and make safe any electrics/lights due to roof leaks from missing/moved roof tiles - leak above P3/4 classroom.
Fourtowns Primary School	Repair section of loose soffit below the pitched roof outside the P1 classroom.
Friends' School	No structural damage to buildings. Boundary/internal fences damaged by falling trees
Gaelscoil an tSeanchai	Over 30 tiles approx. off the pitched roof. Also damage to a flat roof from the storm.
Gaelscoil Eanna Primary School (Glengormley)	Boundary fence around entire site has blown down and been destroyed in storm.
Gaelscoil Ghleann Darach Primary School (Crumlin)	10 streetlights out at front of building - areas have poor lighting.2. Repair/replace metal cover on streetlight at front of building. Wooden fence at bin store collapsed. Repair fence and gate.
Gaelscoil Leim an Mha-daigh	Repair metal fence (Ibex type) in upper playground - panel has come off completely and pupils can now access river. (H&S Issue).
Gaelscoil na Daroige	Repairs needed to the Nursery Mobile the corner facing the main entrance gate; A) Replace approx. 3 linear ft of barge board and decorate to match
Gaelscoil Neachtain	Flat roof felt covering has blown of above store. 3 damaged sections of Paladin boundary fence.
Gaelscoil Ui Neill	Replace damaged cladding on the Side of P7 mobile. Re-secure canopy hanging down over P1 door. Replace 1 wooden gate for P1 garden.
Gaelsoil na Mona	Large metal sheet has come off the front of the building at the top end of the gable all and needs replaced School sign needs secured at the front entrance
Garvagh Primary School	Class change bells are not working - timeclock needs reset from Friday.
Garvagh PS Central MK	Flat roof above tin store leaking.
Gibson Primary	Missing roof tiles in several locations.
Gilnahirk Primary	Replace approx 5 slate tiles from above assembly hall roof - 1 story pitched roof. Replace approx 12 ridged tiles above P4 classroom - 2 x story pitched roof.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Gilnahirk Primary SMK	Replace approx. 5 slate tiles on dining hall roof and also several ridge tiles seem to be loose - pitched roof. Repair / replace damaged guttering around SMK
Glastry College	Replace soffit at 6th form Replace 2 aluminium roof panels on Gym roof Replace exterior skirting panels around mobiles 6 & 10 - 1 large section of skirting off on each mobile Replace missing guttering and downspouts on mobiles 3 and 4
Glenbrook Nursery	Fencing uprooted by tree
Glendermott Primary	Gate post has come away from the gate at Assembly Hall, pedestrian gate.
Glengormley High School	Flat roof leak in Classroom 12F - 2nd floor. Ridge tiles and slates missing - approx 15 various areas.
Glengormley Integrated Primary School	Down spout broken and hanging on exposing sharp edges.
Glenlola Collegiate	Add on tree over hanging the cinema and they have complained to the school. -3 trees down, 2 outside governor's car park.
Glenveagh Special School	Canvas screening round play park is damaged Tarpaulin at back of mobile down. 2 wooden gates at bin compound have completely blown off. Leaver's mobile -part of the guttering has blown off.
Glynn Primary School	One cover on outside security light outside kitchen (lamp post type) cover off and exposed wires at the top isolate and make safe then repair.
Good Shepherd Primary	Damage to wooden roof on gazebo in garden area of playground - a section in the middle has completely detached. Perspex sheet has come off above internal courtyard is getting flooded - have the Perspex sheet but it is cracked.
Grange Park Primary	Replace damaged set wooden doors to SEN Pod, blew off the hinges and glass smashed etc 1 damaged slate roof tile on pitched roof
Grange Primary School (Kilkeel)	School has power but not in the following areas - staff room plus sockets not working , staff toilet and cleaners store plus P3/P4 classroom plus sockets are not working notified to NIE Number of lights not working.
Greenhaw Primary SMK	Broken extractor fan hood on kitchen roof.
Greenwood Infants Primary	Trees down and trees with broken branches in the garden and boundary wall Perspex is loose on playground shelter.
Greyabbey Primary	Wooden fence damaged
Greystone Primary School	Felt has torn away at the cleaner's store roof and another section at the P1 side - flashing is present.



**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Groggan Primary School	Light above main front door blown off leaving exposed wires.Light left switched off. Roof tiles/slates off at both the back and the front of the building.
Hamiltonsbawn Primary School	Ridge tiles moved.
Hamiltonsbawn Primary School MK	Cover on roof for fan has blown away leaving fan exposed.
Harberton Special School	Lean-to roof at the nursery - external seating area - metal seal has come away at the ridge & is only being held on by one screw
Harmony Hill Primary	Fallen trees (not preventing school opening) Replace missing roof tiles at gable of P1 classroom, repair roof on garage at back carpark , tree has fallen on this and caused substantial hole. Replace damaged metal perimeter fence near the garage. Replace gate post along the nursery fence - gate was damaged during storm and pulled out the post.
Harmony Primary	Large section of fascia has detached from library side of building - causing water ingress on window ledges, rainwater is near books.
Harpur's Hill Primary School	Tile off the pitched roof in P2 classroom area Tree down in Nursery playground area and also tree has been up-rooted in Nursery garden - remove from site. Remove and make safe loose branches on trees around centre
Hart Memorial Primary School	Trees fallen at school require action Fir trees down - fell onto pitches and damaged neighbours fencing.
Hezlett Primary School	Guttering has broken in approx. 5 places - Some will need replaced and others need new clips.
Hill Croft School	Roof repair – Mobile Repair damage to pitched roof on transition mobile
Holy Child Nursery	Repair damaged veranda at the back of the school, slanted roof has lifted at the right hand side. School have found various parts of plastic that may be part of this.
Holy Child Primary	Wiring hanging down from roof in foundation area of the school and the wire is going towards the Assembly hall roof - this is hanging down Repair steps to Mobile Classroom. 10 steps going up towards the entrance - they are using the ramp to access this.
Holy Cross Boys' Primary	Refit school bell in the playground that has fallen after storm damage - this bell is linked to the fire alarm. Room 21 top of the building - canopy that goes over the top of the roller shutter - the canopy is not connected to the roller shutter and needs left safe and in use at room 21.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Holy Cross Boys Primary SMK	Replace fallen bricks from the top of the gable wall at the roof of the meal's kitchen.
Holy Family Nursery School (linked to Holy Fam PS	Covered over area outside the Nursery which has a Perspex roof - 2 panels are hanging and damaged. Some others have become loose.
Holy Family Primary, Londonderry	3 No ridge tiles off, 1 canteen and 2 P1 area.
Holy Family Primary School, Magherafelt	1 Ridge tile and also roof tiles to be replaced at the Nursery area
Holy Family Primary, Omagh	<b>SENIOR SITE</b> - 6 edge tiles of the pitched roof - possibly spare tiles on site <b>JUNIOR SITE</b> - Soffit has come away from the area above the staff room and above the side door entrance
Holy Rosary Nursery	Trees need cleared or cut back from pedestrian entrance.
Holy Rosary Primary	Roof leak at reception and into principals toilet - flat roof
Holy Trinity College	Window broken in room 58 - boarded up temp - high level. A fence has blown down at room 12 science, the emergency door has blown off hinge at room 46 and tiles have come off roof at 27 Missing roof tiles reported at several locations. Sheet of Perspex has blown of roof in walkway leading from mobile classrooms to school.
Holy Trinity Primary	The felt has peeled off 2 flat roofs. 1at P5 classroom and other SEN Classroom.
Holy Trinity Primary School	P7 boys toilet - part of the suspended ceiling has come down.
Hollywood Primary SMK	Glass pain in changing room there is a hole ceiling. Skylight.
Irvinestown Primary	Missing lead upstand causing leak in 1cupboard inside the P6 Classroom. Approx 4metres of lead missing - not storm damage as this has been leaking for a while.
Iveagh Primary School	Approx 30/40 roof tiles which are either missing or loose.
Jones Memorial Primary	2no Perspex panels on bicycle shelter - panels off and broken. Replace 3no plastic panels on top of fence in ASD classroom play area. Replace whiteboard in outdoor classroom. Replace 6 missing roof tiles over boiler house Replace polytunnel cover - cover is off and ripped Kitchen doors and worktop in staff room sustained water damage from burst pipe.
Jordanstown School	Roof damage from storm - Flat roof flashing hanging. Staff report additional structural cracking at internal beams. Require Structural Engineer survey and detailed report. Structural cracking evident to various areas - Major cracking to high level roof lights to internal walls.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Kells and Connor Primary School	Roof tiles at front of building – 6 have smashed, several more are loose and need checked/secured.
Kilbroney Primary School	Slates to be repaired/replaced on the pitched roof around the school Plastic cladding missing needs replaced.
Kilcooley Primary	Facia boards (approx. 8 or 9) have been ripped off during the storm - this is all around the school. Fallen trees blocking entrance.
Kilkeel High School	6 steel fencing panels have been damaged and need replaced due to recent storm damage caused by neighbours' trees.
Killard House	PVC frame and glass has blown out due to the storm in the HE Room
Killen Primary	Roof tiles missing in several locations.
Killicomaine Junior High School	Gable wall is coming away at the corner of the school Library
Killowen Primary School	Tree down - wrecked metal fence at front of school.
Killyleagh Integrated Primary	A tree, in the adjoining property, has fallen and could cause damage to the school property. The principal is concerned that it may fall onto the hall of the school.
Kilmaine Primary	Guttering at nursery is broken off and damaged Room18 the skylight is cracked and is leaking. Electric car barrier operated by fob is bent All the Fob doors are opening without the fob - they had a power surge due to the storm. Security issue as the kids can open these doors. Damaged skylight
Kilrea Primary School	Joint in the guttering has all started to leak after storm, top floor outside P6 classroom.
Kilronan School	1.Wooden door to be reattached at the Sand house in the Play area 2. Wooden panelling to be repaired on the shed in the Play area 3.Wooden poles to be removed in the Sensory area
King's Park Primary School, Newtownabbey	Repair 8ft metal fence at the side of the school. Fence hit and damaged by fallen tree Floodlight over the playground is hanging off the wall - light is isolated Urgent - Felt on the flat roof needs repaired - Metal strips have come off on the Assembly Hall and Junior wing roof 2 Storey Building
King's Park Primary School, Lurgan	Replace/replace approx. 7-8 ridge tiles which are dislodged above P4-P7 corridor.
King's Park Primary School, Lurgan MK	Fan in kitchen not working - cover and part of fan has blown off
Kings Road Nursery	Trees fallen and perimeter fence damaged. Metal fence damaged due to storm in back play area - badly bent - sharp pieces

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Kircubbin Primary	No heat or hot water in whole new build of the school - P1/P2/P3, assembly hall, canteen etc - gas underfloor heating.
Kirkinriola Primary School	School sign - decorative stone panel under the school banner has been damaged. Ridge tiles missing from the roof above the main entrance and 1 missing roof tile on adjacent roof.
Kirkistown Primary	Roof of playhouse in school grounds damaged
Knockbreda Nursery	5 pods (wooden sheds with felt roofs) in playground - have been badly damaged, caller wants them disposed of. Repair roof of green metal storage container in playground.
Knockevin School (Castlewellan site)	Fallen tree which has fallen onto residential property and damaged the wall.
Knockloughrim Primary School	Metal fence at the front of the school damaged - Metal fence at the rear of the school damaged. School bells are not working following storm.
Knockmore Primary	Damage to roof of speech mobile classroom. Access safety of electrics in mobile classroom, following substantial roof leak - storm. Dehumidifier required after storm damage. Investigate electrics following water damage from storm at Speech Mobile, needs made safe before they can return to it.
Knocknagor Primary	Repair pitched roof leak beside staff toilets - roof slates have dislodged, plaster on ceiling is bubbling. Plywood panel to be resecure at side of mobile and PVC slips to be secured. Exit of Canteen
La Salle Boys' Secondary School	3 panels missing on greenhouse and 1 is loose
Lack Primary	Guttering on 2 storey building has blown off needs refitted. Flat roof leak in staff room - new extension - ground floor.
Landhead Primary School	Roof Damage: 1 ridge tile has come off the main building, 2 ridge tiles have come off the bike shed and felt has come off the play shed.
Langfield Primary	Fan cover
Larne and Inver Primary School	Several ridge tiles off the pitched roof in the school and some are lying in the guttering. 1 roof leak in P7 classroom - flat roof. 1 leak from the pitched roof coming down.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Larne Grammar School	<ul style="list-style-type: none"> <li>· One roof window was blown off on our technology block – this has now been secured but further work will need to be carried out.</li> <li>· Numerous ridge tiles on the technology block and main school building came off – we are going to require roof works to fix these – the main school building will require scaffolding to repair damages.</li> <li>· Two outside lights in the underpass were blown off – these have now been properly disconnected.</li> <li>· Door to electric cabinet at our hockey pitches was blown off it's hinges – this has now been repaired.</li> <li>· 3g Hockey Pitch mat was blown out of place – this only happened at one side and now has been pulled back into place. There remains a slight ripple in the matting.</li> </ul>
Larne High School	<p>Window in room 18 the frame coming away from the wall.</p> <p>10 Skylight handle window T2 are broken.</p> <p>Tiles and ridge tile off the 3-story block. MEWP will be required.</p>
Laurelhill Community College	<p>Pitched roof leaking at the Art Department above the door at the Staff car park. Dome skylight is missing and needs replaced in the Paper Store - 2 ft sq single storey roof</p>
Lecale Trinity Grammar School	<p><b>Lower Site (Former St Patricks GS)</b>  3 x large Ball Stop fences blown down and destroyed , steel structure totally bent over  8 trees down in grounds  Guttering and Soffit blown off section of building around central courtyard  Tiles blown off section of roof, still being assessed for damage</p> <p><b>Upper Site (Former De La Salle HS)</b>  Large Section of flat roof blown off over technology block. Water pouring in this morning with rain  Section of Flat room blown off over science, water pouring in  External door blew in and frame and door twisted, will need replaced</p> <p><b>Mercy Site (Former St Mary's HS)</b>  Tiles blown off sports hall roof  Tiles blown off garage roof  Guttering and downpipes blown off  Double external doors blown in and has damaged door, hoping door can be fixed  Large tree from neighbours' property blown down across driveway damaging security fence. Tree has been cut up</p>
Ligoniel Primary	<p>Year 7 Mobile - missing felt from the roof - water now dripping inside - bucket under - not affecting any electrics at present - currently dry.</p>

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Limavady Central Primary	Replace the damaged Security light above assembly hall door with LED fitting Approx 16 ridge tiles off ICT suite. Bike shed - Perspex - broken panel.1 wooden fence approx 6 metres down.1 smaller fence not down but loose. Storage huts roofs damaged - polythene Guttering broken in 5 areas around the school.
Limavady Grammar	Replace missing/damaged roof and ridge tiles above exit door at yr 12/13, emergency exit at Lecture Theatre, emergency exit at end corridor stairwell, and above canteen entrance doors. Tiles from the roof have hit the copper pipe inside the greenhouse. Multiple roof leaks in the lecture theatre (pitched roof) Replace metal roof lashings missing from chemistry roof. Roof leaks at S12 and S5 and leaking near electrics so hazardous. Exit door & frame at G2 has broken beyond repair. (Timber Door) Needs replaced. Loose roof tiles and ridges tiles laying on the roofs in various areas around the school.
Linn Primary School	Metal guttering at the rear of the school needs replaced on the 2 Storey Building above P4 Classroom Replace all plastic guttering on one side of the nurture mobile - has detached completely and is damaged.2. Replace 2 plastic downpipes on the nurture mobile.
Linn Primary School (Nursery Unit)	Wooden fencing panels have come down - Located at the back of the nursery and side of the school. Remove large fallen tree located at front of the school.
Lisanally Special School	Replace section of wooden fence at playground Repair wooden fire door in classroom 2 - not opening properly
Lisbellaw Primary	Loose and hanging roof tiles at side of Nursery and close to P6/7 classrooms.
Lisburn Central Primary	Leak in Nursery ceiling, possibly due to the gutters getting blocked with leaves after storm. Flat roof.Few clips have come off guttering and it's hanging loose. Tree fallen but not obstructing entrance.
Lisburn Central Primary SMK	No heat or hot water - one boiler not firing - gas heating cap has come off flu on boiler Cladding off walls around canteen
Lismore Comprehensive	Damaged metal front gates - wind has caught the gates and pulled the poles out of the ground. Gate is now warped. Pipe has come out of spouting at back of RE area and water running down the wall as a result. Repair damaged Catch Net and 1 goal post bracket that has snapped due to storm damage.
Lisnadill Primary School	Repair damage to fascia board and panel at side of mobile hut
Lisnagarvey High	Repair 2 Perspex skylights in T&D building and 1 Perspex skylight in music corridor (main building) - all have shifted slightly, concerned this could cause leaks.
Lisnasharragh Primary	Part of the pitched roof has blown off around the school - ridge tiles missing

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Lisneal College	Door at Assembly Hall, needs a new bracket.
Lisneal College SMK	Wooden fence blown down at Vineyard outside at the SMK.
Lissan Primary School	Remove 2 trees down (1 at P3 mobile and 1 at P4 mobile) Please make necessary repairs to guttering at the side of the school. Loose ridge tile.
Little Flower Nursery School	Perspex roof on covered area has been blown off.
Loanends Primary School	Timber fence 20ft length Fence - A post has come away. The rest of the fence is holding it up. It is leaning out towards the roadside. Wooden picket fence that damaged in storm beside mobile
Londonderry Model Primary	Replace 4 damaged metal down spouts - 2 above rear elevation above Boiler House and 2 above Male/Female Toilets.
Londonderry Primary	Film recently put on the window has blown off. 2 at P7 and 1 at P5. 1 flagpole at the front of the school has been blown down.
Longstone Special School	Fallen tree at back of football pitch. Fallen metal fence (2 sections) that tree has fallen on. Repair several roof leaks in mobile classroom (cleaners store, entrance and toilets) Flat roof
Loreto Grammar School, Omagh	Roof/ridge tiles dislodged and broken on several roofs Damage to metal flashings and lead flashings Broken windows Broken fencing Trees damaged
Lough View Integrated Primary & Nursery School	Significant damage to roof/ceiling collapses
Lowwood Primary	Nursery Unit Roof - Loose tiles on the nursery entrance roof. Loose flashing on the nursery entrance roof. Nursery main roof is missing ridge tile/flashing, has a gap. School roof multiple slates have broken Corner of the roof looks like it is lifting, needs looked at Assembly roof has ridge tile/ flashing missing.
Lurgan College	Replace damaged vinyl flooring in room 19 - floor has been damaged due to broken glass. Replace single glazed broken window (metal frame) Room 19 - boarded up for now. Replace Glass pane in the greenhouse which is cracked (single glazed). Replace single glazed metal framed. Replace damaged roller blinds in room 19 - one blind on the window has been ripped from broken glass. 1 section of Perspex has been blown off the quad porch.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Lurgan Junior High School	Library felt roof and insulation has blown off, slates blown off on two main blocks - approx 10 and glass panes in greenhouse need repaired x5. Canteen path area - a lot of large branches down Repair downpipe outside the gym, has broken away/ disconnected from the joint. 3 dehumidifiers are needed for library caused by storm damage,
Lurgan Model Primary School	H&S - Inspect for loose Sandstone blocks around the guttering and make safe. Some has fallen off in significant quantities leaving a gap. Approx 1 foot of sandstone fell from the roof to the front drive. Awning in playground has Perspex missing from the roof. 1 slate roof of main school has tiles missing School tower has a number of panes of broken glass (single paned). 2 ramps leading to the Mobiles have shifted, leaving gaps between the ramp and the mobile
Macosquin Primary School	Timeclock needs to be set for oil heating due to power cut.
Maghaberry Primary	Significant number of roof slates missing and a number loose and about to fall.
Magherafelt High School	2 Perspex panels off walkway roof plus same on dug out at astro pitch
Maguiresbridge Primary	Front section of copper roof - slight pitch has peeled away the entry hall, library, secretary's office and resource are exposed to the elements.
Malvern Primary	Ridge tile in the guttering at entrance to the school..
Maralin Village Primary School	fallen tree following storm damage at the back of the school. Make necessary repairs to the damaged fence that was hit by the tree.
Markethill High School	Replace 2 areas of damaged guttering outside science rooms. Replace 1 damaged downpipe and guttering in the garden area. Repair damaged canopy.
Markethill Primary School	Replace missing roof tiles / secure loose tiles on both sides of the school. (pitched roof)
Mary Queen of Peace PS (Senior Campus)	1 tree down in the playground and another about to come down near the power cables
McArthur Nursery School	Mesh fence on Bryson street side of nursery - off a hinge
McClintock Primary	Loose tiles at P3/4 and P6/7 mobiles metal clad. Loose tiles on main school building and assembly hall. Facia board blown off and missing.
Meadow Bridge Primary School	School has lost several roof tiles and ridge roof tiles. Area of flat roof the felt has lifted slightly. Ridge & roof tiles blown off during recent storm.
Methodist College	Damage to roofs, gutters, windows (several areas impacted)
Millburn Primary School	Rubber butyl low pitched roof. Timber decking exposed rubber flapping in the wind. Significant roof repairs to two storey school building covering the area of two classrooms.
Millington Primary School	1 metal sign blown out of the tarmac needs replaced and reset. 1 satellite dish hanging off the bracket. Repair Cabling.



**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Milltown Primary School	Broken pane of glass in classroom. Need new carpet.
Mitchell House Special	Gates need attention - 3 off (junior playground) Gulley in car park sticking up, beside garden
Moat Primary	Replace ridge tile from hall roof and fix any others that are loose.
Moirá Primary	Roof tiles down approx. 5 and large part of guttering missing in same area. Velux window in IT jammed open - elec hasn't worked in some time wind warped the frame bucket underneath.
Moneymore Primary School	Ridge tiles off the roof.
Mossgrove Primary School	Attend and make safe/board - One uPVC window and frame blown out on the First Floor One water tower on the grounds has lost one slate. 6 trees are down and branches need cleared on school grounds
Mossgrove PS MK	Ventilation unit in the roof of the kitchen has one side panel completely missing.
Mossley Nursery School	Section of roof damaged and in dangerous condition. A piece of metal fascia board has come loose in the storm and is flapping about above the staff room. Access via ladders
Mossley PS MK	No heat or hot water.
Mount Lourdes Grammar School	Guttering blown off Ridge tiles blown off 6 trees blown down
Mount St Catherines Primary School	Replace Lead flashing that has blown off the roof on the high-level roof.
Mount St Michael's Primary School	Loose tiles some hanging from roof at main entrance to school and nursery -pitched roof.
Movilla Central SMK	Panelling around the canteen building has had one white board blown off
Movilla High	Replace numerous slate tiles that have come off in various areas and also roof guttering / edging on site also - H&S Repair roof leaks in D Block Corridor (upstairs and downstairs) and A block corridor outside A16.
Moy Regional Primary School	Several trees down around school that need removed. No electric to mobile classroom Roof slates fallen from main building. Oil tank door that has blown off Damaged panel fencing at perimeter of school CCTV camera cover has blown off - Can all cameras be checked also that they are working ok after the storm.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Moyallon Primary School	One tile missing from roof
Moyle Primary School	Mesh fencing at nursery play area is damaged
Mullavilly Primary School	Roof tiles missing need replaced around the school.
Nazareth House Primary	S&F numerous slates to the 3-storey pitched roof 4 elevations.
New Row Primary School	Mobile classroom had roof damage following storm causing leak. Power had been switched off. Reinstate power to mobile and make it fit for purpose P4 Classroom rain ingress issues with water coming in through lights. Roof leak in mobile 4 - flat roof - patch repair.
New-Bridge Integrated College	Internal water damage due to roof leaks (no evidence of broken tiles) and a wall fan was blown into a classroom leaving a hole in the wall
Newry High School	4 Ridge tiles off the roof on back building and 1 roof tile on the front above nurture unit.
Newtownards Model Primary	Bangor blue slate off P1 G classroom
Newtownhamilton High School	Replace Approximately 17M of spouting has come away from ST building
Newtownhamilton Primary School	White strip needs replace on the outside of the Aluminium window in the library.
Newtownstewart Model Primary	Lead flashing on a pitched roof at the senior end has blown up in the storm.
North Coast Integrated College	Damaged roof tiles in main building and mobiles
Oakfield Primary School	Lead flashing missing at the upper floor - Staff area. Insulation cover for the heating pipes outside on the roof needs repaired/replaced.
Oakwood Integrated Primary School	No damage to premises but number of trees down
Oakwood School (former St Mary's, Saintfield)	Roof leaking.
Old Warren Primary	Repair external wooden entrance door to oil tank enclosure beside SMK - wooden support for door has detached from concrete, door hanging on and is not secure.
Omagh Academy Grammar	Missing roof finish issues at various locations

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Omagh High	Electrics telephone cable Roof damaged over HE Rooms - Significant. Insulation has blown off front elevation.
Orchard County Primary School	Damaged perimeter fence (metal mesh fencing) - areas have fallen down and one area is hanging over the foot path.
Orritor Primary School	Wooden door has come off the frame and needs replaced at the back entrance to the Nursery. 3 No Perspex panelling to be replaced at the Nursery porch RJ alarms fitted CCTV. Since storm - images are distorted on camera.
Orritor Primary SMK	Extractor fan mesh cover is missing and needs replaced on the window in the kitchen
Our Lady and St Patrick Primary School	Roof tiles missing above P1 classroom to hip.
Our Lady and St Patrick Primary School SMK	Broken roof tiles above SMK replace roof tiles.
Our Lady and St Patrick's College	<ul style="list-style-type: none"> <li>· Fencing panels down around the perimeter of the College backing on to residential properties.</li> <li>· One tree has come down in our Courtyard area.</li> <li>· Metal panels have come off the side of our Sports Hall.</li> <li>· Fixed signage around our 3G pitch has been blown away.</li> </ul>
Our Lady Of Lourdes High School	Insulation has blown off the large heating plant located at Sports Hall and need replaced.
Our Lady Of Lourdes HS MK	Damage to guttering at side of the kitchen.
Our Lady Queen of Peace P.S.	The heat won't come on in the primary.
Our Lady's Primary School (Tullysarran)	Pitched roof of dining hall - approx. 6 roof tiles are dislodged, they are still on the roof.
Our Lady's/St Mochuas PS	Replace tiles and the solar panels on the pitched roof that were damaged in the storm.
Parkhall Integrated College (Junior)	Astro pitches -the cover has lifted in 2 different places due to the storm.
Pond Park Nursery	Perspex panel has come off outdoor sand pit Letters of the sign at the front of the school has blown off and need to replace.
Portadown College	Slates missing and some loose tiles are hanging all round main building plus mobile 1

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Portaferry Integrated Primary	Damage to pitched roof of school - several tiles have blown off at the front and back of the building.
Portrush Primary School	Fallen trees and rainwater goods need repairs
Portrush PS Central MK	Pitched roof leak above the windows at the front of the school. not affecting any electrics at present - basin down to catch the water - this is in the main food prep area.
Portstewart Primary School	large black gate which is held up by 7ft black posts have come down and ripped up the foundations of a small wall at the play area. Unknown number of roof tiles have come off at P4
Portstewart PS MK	Replace 2 ridge tiles and approx 3 roof tiles on kitchen roof. (pitched roof)
Poyntzpass Primary School	Replace doors on 1 water tank on roof - has lost its doors and the tank is exposed - access with ladders No heat in mobile classroom - gas heating - electric heaters in place
Poyntzpass Primary School MK	1 fan grid has blown off the fan in the kitchen.
Presentation Primary School	Roof tiles near back door of school need re-fixed after storm. Lead Flashing above main school entrance has come out of wall.
Primate Dixon Primary School	Tree fallen at infant steps
Queen Elizabeth II Primary, Trillick	Roof tiles missing in several locations. Safeguarding measures advised in the meantime.
Queen Elizabeth II Primary School, Pomeroy	Roof tiles missing in several locations. Safeguarding measures advised in the meantime.
Railway Street Nursery School	Tree fallen onto roof of Nursery building.
Rainey Endowed School	<ul style="list-style-type: none"> <li>* Three mobile classrooms and toilet block significantly damaged</li> <li>* Carpet on astro-turf pitch lifted in several places</li> <li>* Perimeter fence warped and tree fallen</li> <li>* Slipped roof tiles</li> <li>* 2 overhead panels removed on walkway at tennis courts</li> <li>* Fallen trees across site</li> <li>* Table tennis tables damaged</li> </ul>
Randalstown Central Primary School	Canopy at girls' entrance located at front right-hand side of building - felt has lifted and concrete below has disintegrated. Staff have removed pieces of concrete.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Rathfriland High School	Repair damage to both slopes of Home Economics roof major damage to dining room elevation and water penetration into classroom Check electrics in HE stairwell, ongoing water penetration due to roof storm damage.
Rathfriland High SMK	Missing roof tiles to both dining room and meals kitchen roof. Reset in place uplifted roof tiles to rear side of meals kitchen roof (single storey) Loose louvre in roof fan.
Rathore Special School	tidy up and repair fencing and a tree fallen Replace approx 20 roof tiles on mobile J9/J10 High level window in J5 is loose from frame as it was caught by the wind, hinges are damaged as a result and window is stuck open , it has been taped. Part of tiled pitched mobile roof in J9 and J10 (quiet room) has come off , can see daylight through it and also metal flashing is missing.
Regent House	Roof panel for greenhouse - Perspex roof panel missing Roof trim has broken off the music flat roof - caretaker has it stored on site ready to be fixed. 2 damaged windows in the Performance hall and staff room - Frames are hanging down. (metal frames) Sports hall double fire door (wooden) - was ripped off during the storm. Staff have temporarily secured the door.
Richmount Primary School	2 Perspex sheets are broken on bike shed.
Riverside School	Fault with 1 CCTV security camera located in car park area (Number 8) it is rotating and not operating properly.
Roan Primary School	Ridge tile off the old school building - pitched one storey.
Roddensvale School	Approx 6 slates have come off pitched roof off main sports hall.
Roscavey Primary	tiles have come off roof and there are some loose ready to fall plus felt on same side is viable plus fasica board has come off plus leak in assembly hall.
Rosemount Primary	2/3 sheets of Perspex blown off in nursery enclosure. Wooden fence and posts damaged by storm at the back of the school.
Rosetta Primary	30m of fencing damaged and part retaining wall. Reinforce existing Harris fencing which is loose. Make fencing and pergola safe. Missing roof tiles above mens' and boys' toilets. Damage to wall separating the school and neighbours garden
Rosetta Primary SMK	Polystyrene balls coming out of the wall in the kitchen caused by 2 separate holes - 1 in the ceiling and 1 behind the heater.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Rossmar School	1.Re-secure Slip which has blown off the green house roof - caretaker has this on site. Replace missing down-pipe for green house.2. Repair damaged double aluminium fire doors. Rm G97 has no power at sockets - No fuse tripped. No power at gas panel - Gas engineer has been out but nothing wrong with panel. Problem only occurred since Storm.
Rostulla School	Trees down need cleared - Not obstructing any roads only pathway to gym hall. Concrete slabs are lifting to main entrance to playground - KS2 - H&S tripping hazard.
Round Tower Integrated Primary School	Evaluate and make safe any electrics effected by various roof water leaks due to storm damage, to allow repairs to be completed by roofing contractors Removal of damaged asbestos-containing decorative textured coating (TC) to several areas where water damage has occurred due to storm damage. Staff room -Disconnect electrics and remove any light fittings mounted on timber, remaining lights will be removed along with ceiling as plasterboard /Artex ceiling to be removed. A section of roof blown off in storm. School have reported possible asbestos in roof which has been forwarded onto contractors. Wooden fence has been blown over by the storm.
Sacred Heart (Rock) Primary School	Steel green palisade fence damaged due to fallen tree.
Sacred Heart College	Outside window at upper school - first floor - 4mm laminate - boarded up and the front door of tech block - also toughened glass 6mm - badly cracked.
Sacred Heart Grammar School	Damaged roof tiles resulting in damage in assembly hall.
Sacred Heart Primary (Tattyreagh)	Loose slates
Saintfield Central SMK	Replace metal protective cover on compressor housing for the walk-in fridge, electrical isolator also exposed, cage has also blown off and needs replaced. Cage has blown off in the wind
Saintfield High	Replace 20 roof tiles in 3 areas.
Sandelford School	Metal fence is damaged and needs repaired at the old mobiles. Bar on the metal gates not closing properly at the Bus area Guttering to be cleaned and repaired around the building. Roof tiles missing need replaced around the building - approx 20 School reported greenhouse had been damaged in storm and was blocking entrance to the school.
Scarva Primary School	Trees fallen at both front and rear of school, also roof tiles missing.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
School of Music - Fortwilliam Complex	Carry out fence repairs due to storm damage
Seagoe Primary School	Blown off guttering and down spout in P4/5 mobile
Seaview Primary	Roof tiles are displaced all over the roof sensor room leak 2 tiles missing off the girl's toilets roof. Both rooms are out of order. Door on wooden shed in playground has come off and has blown away.
Sion Mills Primary	Inspect and repair fire alarm panel
Sixmile Integrated Primary School	3 trees down at back of playground. Replace roof slates on roof at back of school.
Sperrinview School Annex (former Cookstown YC)	Shelter of pod has come off and needs to be re-secured.
Sperrinview Special School	Ridge tiles damaged.
St Aidan's Primary (Magilligan)	The left side of playground and storm drain blocked causing standing water. Remove to make safe large broken high-level tree branches located beside the polytunnel at the right-hand side of the playground. cherry picker or other lift will be required.
St Aidan's Primary (Magilligan) SMK	Sections of galvanised metal spouting at back of canteen and the main hall (approx. 50m) - have blown down, area has been cordoned off.
St Aloysius Primary	Damaged gutters following storm damage and gutters are loose after storm damage. Nursery - covered play area - the plastic cover is broken and needs replaced Make repairs to the damaged cable rail holder that is on the roof. Fallen trees
St Anne's Primary School	Large tree to be removed from the front entrance of the school - tree near electric cables. Remove tree from entrance to allow access
St Anthony's Primary School	1 tree fallen from derelict land (former school) onto school property
St Bernards Primary	Damaged branch from tree at front of school. Top gated second tree down.
St Brendan's Primary School	Section of Roof damaged. Pitched roof of main building - several dislodged ridge tiles and slates in various locations.. Repair PVC guttering on main building beside junior playground and on mobile.
St Brigid's College SMK	A) Replace Double timber emergency Exit to the Corner of Dining Hall, facing boiler house. B) Replace double timber doors.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
St Brigid's Primary (Altamuskin)	Whole back of Mobile 2 has been blown off in the storm and the insides/fibre glass is coming out
St Brigid's Primary School (B'Money)	Tiles have blown off P2 roof (pitched) Damage to sign at front of school.
St Brigid's Primary School (Drumilly)	Wooden fencing around kids play area has fallen.
St Brigid's Primary School (Glassdrummond)	Casing around the boiler is missing and needs replaced at the Mobile Classroom Roof tiles missing at the back of the school. Spouting to be replaced Ceiling tiles to be replaced in the P6/P7 Mobile Classroom due to roof leak Window in P5 mobile classroom broken.200MM x 420MM
St Brigid's Primary School (Tirkane)	Trees fallen on lay by and play area. Metal fence damaged.
St Brigids Primary SMK	Electric shutter hanging off.
St Caireall's Primary	Roof slates have been blown off the roof above the P1 classroom. Seals have blown off the skylights.
St Canice's Primary (Dun-given)	Section of flat roof felt covering off above Classroom 2.
St Canice's Primary (Feeny)	Replace 2 wooden perimeter fence panels located between football pitch and graveyard - both panels have fallen, they were damaged by an uprooted tree.
St Caolan's Primary school	Damage to roof requires repairs.
St Catherine's College	School sign to be reattached at the Barra Building - Front Entrance - High level 1 Window frame damaged and glass broken - window needs replaced in the Photography Office - Secured for the weekend. Roof slates loose and missing need replaced/replaced on the Main Convent Building.
St Catherine's College MK	Partial electric in the school meals kitchen
St Catherine's PS, Barrack St Site	S&F approx. 12 roof slates to 2 storey pitched roof. Refix section of guttering to same roof.
St Catherine's PS, Barrack St Site, SMK	Broken single glazed pane to the Dining Hall.
St Ciaran's Primary School	2 flat roof leaks (one over staffroom and one over Room 3) Damage to roof of bike shelter - Health & Safety (sharp edges) - area has been cordoned off).



**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Clare's Abbey PS - St Colmans campus	6 mature trees down in play forest which are extremely dangerous. These need to be dealt with as a matter of urgency due to the dangerous nature.
St Colmans High and Sixth Form College	Repair of tiles on roof at R2 send electrician to check all light and sockets before kids and staff move in. Damaged roof and porch. 1 leak from pitched roof going into the valley in R2 - ladder access
St Colmans Primary School (Annaclone)	Aluminium tile flashing has blown off Nursey, water ingress at the lobby.
St Colman's Primary School (Bann)	1 ridge tile loose on the assembly roof.
St Colmcilles High	4 ridge tiles and 6 slates off due to storm damage - cement fibre. Damage to black metal fence on playing field behind goal area due to fallen tree. 1 football post is damaged in playing fields, leaning to one side.
St Colmcilles High SMK	Carry out water jetting to clear blockage to staff toilet - the only staff toilet is backing up, suspect blockage was caused by storm weather.
St Colmcilles High SMK	Remove tree branch from flat felt roof above canteen, repair/replace damage to hopper box which has detached, assess flat felt roof for any damage - branch from large tree has hit.
St Colmcille's Primary	Alarm
St Colmcille's Primary	Guttering, soffit and fascia blown off above Assembly Hall and into nursery play area below. Make safe Perspex sheeting to Bicycle Port. 3 wide wooden boundary fence panels have blown over between playpark at left-hand side of school and a neighbour's garden.
St Colms High, Twinbrook	Roof cover leaks - First floor - flat roof (World of work) classrooms and Assembly Hall Skylight on flat felt roof - blew open with Storm.
St Colm's High School, Draperstown	Semi pitched roof leak in classroom (2 x story). Semi pitched roof leaks in Art Room (2 x story). Flat roof leaks in Tech Saw Room (1 x story). 3ft round dome skylight has come off the roof outside VP office in the storm - secured with plywood for a temp fix. Wooden fire door in English Mobile, has blown completely off the hinges on Friday due to storm, caretaker has boarded up area but door needs replaced as it is beyond repair.
St Colm's HS MK	Door at bin area has blown off the hinges.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Columbas High	Damage to exterior metal fence (approx 50 ft) from fallen trees (from inside the school) Soffit has blown off in different parts of the roof area from all over the school - some is fire board and some aluminium Repair flashing that is exposed above room 13 and 14 - Approx 30 ft of lead flashing all lying on room
St Columba's Primary (Clady)	Inspect and repair all electrics following storm damage - electric cable outside has fallen onto playground - fire alarm and intruder alarm sounding. Make safe loose guttering to rear elevation of school and replace if required. Make safe damaged roof to the solid wall constructed external store beside the bin compound. Carry out replacement of felt covered roof on alike for like basis. Replace the covering to the canopy above the entrance door of the mobile classroom.
St Columba's Primary School (Garvagh)	Following the storm the electric went out and the intruder alarm will no longer set. Please evaluate and repair. Following the storm the electric went off and now the timing clock is out of sync for heating. Gas heating is coming on at the wrong time and school is cold.
St Columb's Primary School (D'Martin)	Electric cables blowing from flat roof within the school
St Colum's Primary School (P'Stewart)	Section of PVC guttering has completely detached and is damaged. Located beside the staffroom.
St Comgalls Primary, Bangor	Plastic cover and concrete edge of roof has come off in KS1 area - 2 storey pitched roof.
St Comgall's Primary School, Antrim	1 large tree has fallen down and has hit another tree and is leaning up against it.
St Connors College Junior Site	Old mobile tin torn away from the back off it. also noticed the chipboard floor needs looked at. Very concerned about safety of mobile.
St Conor's Primary	Roof leak - rainwater coming through ceiling at P4 pitched roof - two storey. Flat roof leak.
St Dallan's Primary School	Ceiling tiles to be replaced around the school due to water damage
St Davog's Primary (Bel-leek)	3 Metal fencing panels missing need replaced at the front of the school between the play park - Health & Safety 2 large trees came down in the storm needs to be cleared away.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Dominic's Grammar School	Slates have slipped on the roof. Slates have been removed from the roof. Branches have fallen off some trees. Some windows had been forced open due to high winds The barrier at the front gate was broken.
St Eithne's Primary	S&F replacement roof slates to the P3/4 Area.
St Eugene's Primary (Londonderry)	Make safe dislodged cross on roof at Senior Site, set aside for re-use. Replace missing and dislodged roof slates.
St Fanchea's College	Remove 3 small trees from main driveway that are blocking main route in Replace glazing in double glazed unit of Bursars office. Push button operated sky lights are not opening in assembly hall, no power going to them, motors may be faulty. Damage to metal perimeter fence at football field damaged by a tree falling on it Replace 2 sets of goal posts and catch nets in football pitch area
St Finians Primary	Missing/damaged ridge tiles over P7 classroom and roof tiles over Pre-school
St Francis of Assisi Primary School	Guttering has blown down inside the courtyard area.
St Francis Primary (Drumara-road)	Electrical and Mechanical disconnections of all supplies to mobiles damaged during storms at St Francis PS Drumara-road, to allow repair works to be carried out, and on completion of all building repairs Trees fallen at school require action. One tree has fallen through mobile classroom roof. Provide site guard fencing to cordon off area of boundary fencing to prevent access to the school and cordon off area to the side of the dining hall to prevent pupils accessing. Provide structural engineers report on the damaged mobile classroom to establish if it is safe to continue to use the section of mobile classroom not damaged by the fallen tree. Missing and broken ridge tiles to the roof over the entrance lobby. Provide tarpaulin sheet to cover damaged area of the mobile classroom and help reduce the water ingress to this area.
St Francis Primary School	Year 2 block has tiles off and guttering has come down. Bunscoil Block metal capping has come off 1. P6 gable wall tiles disturbed and guttering due to storm -pitched roof 2. Flat roof has completely blown off above the electric supply room and water is now leaking into that room. Faulty grate in back playground. 3 8ft trees have been blown down - In 3 different locations around the school - The roots are still in the ground. Wooden fence has been damaged at the P1/2 play area - approx. 15ft of it is damaged & collided with a roof causing damage.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Francis' Primary School (Aghaderg)	Please rebed/replace approximately 15 no. ridge tiles have blown off in various locations across the school roof.
St Ita's P.S.	Re-secure / replace felt on the shed roof.
St James' Primary School	Flat roof - leak in the store in Classroom 1 in the Nursery & dripping onto the light - heavy rain last night - please make safe or isolate electrics affected until roof repaired. 1 outside water tank which was on the roof of the nursery (8x6) has blown off and caused damage to the 3ft wooden fence. Facia board off the assembly hall wall
St John the Baptist College	Tree debris needs cleared - will not prevent school opening. 5 louvre blinds were ripped off the windows during the storm in classroom in the top block (windows already dealt with) 6 windows in classroom on the top corridor (single glazed, metal frames) - window units have detached from frames leaving gaps.
St John The Baptist Primary	Slates off main roof and panel off a mobile
St John the Baptist Primary School	Large section of fencing (mesh) has fallen at sports pitch.
St John's Business and Enterprise College	Roof tiles missing in the Gym area Flat roof leaking in the Girls toilets. Wooden panels missing from around the oil tank at the back of the school
St John's Primary (Coleraine)	Ridge tiles to be replaced at the pitched roof at the link corridor to SJP Roof tiles to be replaced at the link corridor to SJP. 1 cover to be replaced on the emergency light outside the Foundation Classrooms. Rain getting in. Chimney cracked due to high winds
St John's Primary (Dernaflaw)	1 length of guttering (approx 3-4 metres long) has blown away in the storm - above the Junior playground area.
St John's Primary School (Gilford)	1 tree has fallen inside the property and caused damage to the Green Metal Perimeter fence, knocking down about 5 panels and this is partially blocking the entrance.
St John's PS MK (Swatragh)	Part of the flat roof is missing on the kitchen due to the storm - edging has come off and possibly part of the top - unable to see - water housing above this.
St Joseph's (Madden) Primary School	Roof Repairs - Single loose tile on the pitched roof at the entrance to the school

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Joseph's Boys High School (Newry)	Roof Repairs - High Level - significant number of missing and dislodged ridge tiles and roof slates to the school roof - cherry picker/scaffolding needed. Signage Contractor and hoist required. The letter "O" is hanging loose from school sign at front of building & school are afraid it will come down.
St Joseph's Boys High School (Newry) MK	Make safe, replace, secure significant number of roof tiles above the school kitchen.
St Joseph's Boys' School, Londonderry	Missing and dislodged a significant number of ridge tiles and roof slates to the school roof - cherry picker/scaffolding required. Inspect and repair solar panel.
St Joseph's Boys' School, Londonderry SMK	Significant number of roof tiles above the school kitchen off.
St Joseph's College Secondary	Broken window in the link corridor - single glazed small rectangle window - boarded up at present Approx 9 ridge tiles have come off the corner of the school
St Joseph's College Secondary SMK	At kitchen entrance door - inner side small leak following storm. Flat roof inspect for damages/leaks.
St Joseph's Convent Primary School (Newry)	Replace 1dry verge to the edge of the roof of Key stage 1.
St Joseph's High School (Crossmaglen)	Downpipe 2 storeys high in student yard, has come away, Water is coming down the student entrance door in the back yard.
St Josephs P.S. (Lisburn)	2 electric heaters in after school club not working Panel missing from roof above principal's office - part of the soffit also at breakfast room - another section of soffit and a wall/fence has come up from base. Fallen trees damaged boundary fencing.
St Joseph's Primary	PVC from the Canopy outside P2 classroom has been ripped off. 3 large, double-glazed windows cracked in P5B.
St Joseph's Primary (Donagh)	Replace wooden boiler house door - off hinges and split in middle NIE have attended and removed the wires, and the tree now needs moved
St Joseph's Primary (Drumquin)	Perspex cover on mobile canopy blow off - needs to be replaced.
St Joseph's Primary (Ederney)	Water getting into fire alarm sensor in outside mobile Mobile classroom felt roof significant damage and rain ingress. Library mobile.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Joseph's Primary School (Bessbrook)	Flat roof leak to front mobile. Water coming into electrics, but power turned off and not in use at the minute.
St Joseph's Primary School (Caledon)	Remove large branches that have already fallen and any that are loose and likely to fall over the car park - H&S
St Joseph's Primary School (Killeenan)	Tree down inside the school and has taken down a section of the metal link fence that secures the school/play-ground.
St Joseph's Primary School (Stiles)	Cable hanging of roof at high level (2 story building at rear entrance onto playground ) Multiple trees have fallen. Following the removal of the trees on the road boundary, please purchase Heras fencing for the openings and make safe. Following the removal of the trees within the school grounds, please repair IBEX fencing.
St Josephs Primary, Carnacaville	Pitched roof at the front of the school has damaged and missing roof tiles these are possible suspected asbestos roof tiles
St Kevin's College	PVC cladding has come off the Math Block. Felt roof off on mobile classroom. Single aluminium door at maths - door closer is broken. Broken panes x3 maths area DG, cracked window in ICT and cracked at languages corridor. Replace single aluminium door of Math block.
St Killian's College, Garron Tower	Roof damaged on the Dunmaul Building, Tree down at pitches and fell onto fence, Goal posts broken on football pitch.
St Lawrence's Primary	Fallen tree which school have already arranged to remove - perimeter fencing repairs required.
St Louis Grammar School, Ballymena	Number of fallen trees. All areas have been made safe and an external contractor has been engaged to remove all debris off site and reinstate areas damaged.
St Macartan's Primary School	The fire alarm needs checked over due to the battery back up having to kick in during the storm over the week-end and the fire alarm going off Intruder alarm needs serviced due to the battery back up having to kick in during the storm Broken and loose tiles on the pitched roof on key stage one
St MacCartan's Convent Primary School	Ridge tiles missing need replaced at the Mobile Classroom
St MacNissi's Primary School (Larne)	Approx 35 damaged/ missing roof tiles throughout school building

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Macnissi's Primary School (N'Abbey)	Flat roof in main hall - rain leaking in under the tiles. Drain Jet - playground flooded - storm drains are blocked. Inspect drains at front as well - P2 area smelling - possible jetting needed inspect jet etc
St Malachy's College	Section of felt roof on gym and rain water seeping through to floor
St Malachys High	Heating system timing is out of sync due to the power going out.
St Malachy's P.S. (Bangor)	Wooden fence down around the playgroup area
St Malachys Primary Castlewellan	Pitched roof of building - numerous slates are dislodged in various locations, concerned they will fall near the front entrance, the playground, the canteen, and the sports area.
St Malachys Primary Kilcoo	Ridge tiles have come off the canteen roof. Water coming from the ceiling at P2/3 classroom, at the entrance. Flat roof above the entrance.
St Martin's Primary	Fallen trees reported on school grounds from adjacent parish hall - one in particular a risk to P1 classroom mobile. Replace damaged boundary fence panels following fallen trees. (Tree removal on another order) also ridge tiles and roof tiles to be replaced.
St Mary's Grammar School	Perimeter fence damage. Sports hall window broken Ridge tiles/roof tiles dislodged over 20sqm area on one building and an area of tiles and spouting damaged on an other area
St Mary's High School (Newry)	Downpipe at the front of the school have come down, top section Downpipe broken away from the guttering at the rear of the school. Flashing has lifted from the window at room 5G.
St Mary's Nursery Unit	A) S&F 2 replacement Perspex type panels to the Nursery Canopy. B) Refit lifted edge roof tile above Classroom 1, pitch facing.
St Marys P.S. (Comber)	Since storm they have no internet or phone lines working, lights on *all elec and heat fine someone needed to inspect data network/ switches large branch 8ft in length is hanging at the school park area high level - area cordoned off
St Marys P.S. (Kircubbin)	Trees fallen. One tree blocking lane to NIE sewage plant requires removal.
St Marys P.S. (Portaferry)	20 ridge tiles smashed. Attend and replace ridge tiles. Perspex on roof outside nursery play area coming loose since storm - Clear Perspex shattered on sides also causing H&S issue. Approx 40 ceiling tiles water damaged by roof leaks following repairs to the roof.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Mary's Primary (Brookeborough)	Broken Skylight in Staff Room on back of school roof. This is a tiled pitched roof on the higher level. Damage to exterior wall at front of mobile (timber coated with cement) - cement has disintegrated which leaves two large holes, timber is exposed. Concerned about water ingress.
St Mary's Primary (Killesher)	20 tiles down including some ridge tiles.
St Mary's Primary (Maguiresbridge)	Emergency voice communication system - line outside the P4 Classroom to communicate with the office - keeps ringing to the office, going off every 10 mins.
St Mary's Primary (Mul-lymesker)	Pitched roof leak - leak coming into P2/ P3 toilets
St Mary's Primary (New-townbutler)	IT cable laying across the playground initially reported but advised by school principal that this could be live cable. Trees required to be cut down in playground - H&S issue - have it cordoned off also same area metal fence is damaged CCTV wires have come down in the storm leaving the cameras.
St Mary's Primary (Tee-more)	Tree Fell onto football pitch and boundary fence is damaged.
St Mary's Primary School (Aughnacloy)	Greenhouse has been damaged in storm. Glass to Greenhouse has come away and round the car park and needs cleared up. Wooden fence at mobile. Posts have broken off at ground level and fence down. Replace guttering and fascia board that has blown off in the storm. Allow for replacing rotten timber soffit below for secure fixing of new fascia and guttering.
St Mary's Primary School (Banbridge)	Tree fell on 6-foot-high metal fence and tree is now removed by EA Grounds. There are 2 posts and 3 panels damaged on the fence which needs repaired.
St Mary's Primary School (Cabra)	Replace/ reface brickwork to column at right of front entrance
St Mary's Primary School (Cabra) MK	Flat roof leak was dripping this morning into the kitchen but has stopped now - access with ladders.
St Mary's Primary School (Derrymore)	Fallen tree that has also damaged to perimeter fence.
St Mary's Primary School (Derrytrasna)	Trees fallen at school
St Mary's Primary School (Draperstown)	Guttering outside P1 classroom has been ripped off the wall



**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Mary's Primary School (Dunamore)	Part of roof blown off to P5 mobile. Replace roof ridge tiles that are missing 2 at front of school, plus roof tiles missing above P3 classroom, tiles at back of school at edge of P2. 3 trees fallen onto pitch
St Mary's Primary School (Glenview)	Fascia board blown off main building
St Mary's Primary School (Granemore)	Replace sheets that have blown off Canopy in the Nursery area roof and also at P4 mobile PVC has come off canopy at front door of mobile Cladding around the outside of the kitchen - a cladding piece has come off in the storm.
St Mary's Primary School (Lisbouy)	sports hall ladder height according to caller ridge tiles and tiles - approx 10 in total
St Mary's Primary School (Mullaghbawn)	Remove tree branch which has fallen onto the mobile roof - approx. 1ft diameter branch from a tall tree has hit the mobile.2. Repair damage to pitched roof - several ridge tiles Several loose tiles and 1 loose ridge tile on the pitched roof over the Assembly Hall. 1 panel of the 6ft high steel perimeter fence was damaged during the storm. It is at the back of the school and the school is secure. One pane broken in the Mobile Classroom Storeroom - boarded and secured for now.
St Mary's Primary School (Pomeroy) MK	Cover is broken and damaged needs replaced on the air vent in the kitchen.
St Mary's Primary School (Rathfriland)	Some tiles on the pitched roof have slid down into the spouting and another one is loose.
St Mary's Primary School (Stewartstown)	Downspouts damaged at Resource Room&P7, Outside of Sports Hall at disabled toilets and at back door. Gut- tering, above boiler House and at the back door. PVC Facia board damaged.
St Mary's Primary School Newcastle	Secure soffit panels to the canopy of the P1/P2 classrooms. School report one panel has fallen and several others here are about to detach.
St Mary's Secondary (Lima-vady)	Assembly hall roof - the rubber butyl has blown off & metal trim. Damaged guttering around the assembly hall. Repair / replace badly leaking sky light in H.E room. Gutter is broken around the RE Dept due to the storm - needs replaced and new clips - single storey. Badly damaged roof over the assembly hall approx. 300m sq.
St Mary's Star of the Sea Primary	2 guttering from the entrance to the kitchen and the back of the sports hall/alleyway have been ripped off in the storm Slates and ridge tiles on pitched roof need repaired

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Matthew's Boys and Girls' Primary	Fascia sockets and cladding is ripped off nursery outside classroom Guttering at P1 and P5 is broken off Roof leak in room 12 causing ceiling tiles to come down - pitched roof Ridge tile missing on P5 roof - pitched roof
St Matthew's Primary School (Magheramayo)	Roof leak
St Michael's Primary School (Clady)	Replace tile on pitched roof on new part of building - tile has smashed. Carry out water jetting - all drains around the school are overflowing following the storm. Rotted timber fence badly damaged in the storm. Supply and fit 1.8M high Ibex (black) to left- and right-hand side of entrance with 1 gate in each.
St Michael's PS (Dunama-nagh)	Part of the roof has blown off over the new extension Investigate extent of damage and carry out the safe isolation of electrics if necessary when safe to attend site following storm damage - Pitched roof has blown. 2 No interactive White boards damaged during storm Eowyn - classrooms flooded so possibly water damaged.
St Ninnidh's Primary	Roof slate missing several locations and also perimeter fence damaged. Repair large wooden boundary fence between school property and graveyard - approx. 80% of the fence has fallen. H&S & security concern.
St Oliver Plunkett Primary	Outside flashing at the P2 toilet has some has come off and some still hanging. Down pipe has come away from the wall and now only held on with one bolt - top one has come away.
St Oliver Plunkett Primary (Strathfoyle)	Fascia & soffit boards, blown off and a few loose
St Oliver Plunkett's Primary School (Ballyhegan)	No Heating in back building. Fault in system needs cleared. Replace sections of fencing to football pitch damaged by fallen tree.
St Patrick's Academy, Lis-burn	Roof in assembly has missing slates and some hanging off H&S issue -pitched roof
St Patrick's Academy, Dunganon	*Greenhouse smashed - cannot be repaired * Loose fence posts and panels * Bent gate post * Stays for ball stop nets have snapped * Damaged portable gate posts * Fire Assembly point sign damaged and cannot be repaired * Roof tiles damaged

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
St Patrick's and St Brigid's College	1 broken window on 2nd floor - metal frame, 1 dislodged pipe at the back of the school, 1 fascia board blown off the top floor. Replace damaged hinges on external wooden fire door.
St Patrick's and St Brigid's College SMK	Issue with the extractor in kitchen - intake fan making a loud noise - something may be stuck in it
St Patrick's College, Dungan	Damaged metal guttering above two storey block. Please attend site to make safe 3Nr. glazing panels and return to reglaze to Greenhouse. Health and safety issue playground and access to Mobile Classrooms restricted. High level fence that protects the windows has broken in the storm. Flat felt roof covering/roof leak above Mobile Classroom 24/25.
St Patrick's College (Banbridge)	Roof Leak in assembly hall
St Patrick's College (B'Mena)	Tree down at front of site and 3 others are leaning
St Patrick's College (Dungannon)	A large number of gutters are hanging off all over the school and they have had to close the carpark for H&S issues
St Patrick's College (Maghera)	Section of roof has blown off at St Mary Building
St Patrick's College MK (B'Mena)	Flat felt roof leak in boiler house - leaking onto cables but doesn't appear to have affected electrics or equipment so far.
St Patricks P.S. (Holywood) SMK	Porch going into canteen - the wooden ceiling is exposed as ceiling tiles have fallen off.
St Patricks P.S. (Saul)	Controls need to reprogramme the heating settings following storm - times - oil heating
St Patrick's P/S Legamaddy	5 tiles of the pitched roof at the side and back of school
St Patrick's Primary (Castlederg)	Replace approx. 1 slate tile down at extension roof above girls toilet - pitched 1 story roof and also re-secure roof glazing at Nursery outdoor play area Repair damage to metal panel perimeter fencing Repair damage to flat felt roof at P2 entrance area. patch up to 16m2 granulated felt.
St Patrick's Primary (Derrygonnelly)	Flat roof has blown off the Assembly Hall
St Patrick's Primary (Gortin)	Small playhouse to be taken away, catch net poles bent at base cut of bent section and refit into sleeves

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Patricks Primary Bal-lynahinch	Tree down path leading to dining Hall /nursery. Building Supervisor has made access achievable for now, but tree needs to be cut up and taken away.2. Branches hanging down from tree.. Replace broken PVC down spout at side of KS1 area
St Patricks Primary Burren-reagh	Various roof slates missing that would not prevent school closure.
St Patrick's Primary School (Aghacommon)	Loose cable to be made safe across infant playground.
St Patrick's Primary School (Annaghmore)	Roof leak in the main corridor - lights / Wi-Fi cables are surrounding it. (flat roof)
St Patrick's Primary School (Aughadarragh)	Mobile fascia board blown off - tiles loose Boiler control panel blew.
St Patrick's Primary School (Ballymaghery)	Several trees around school site with one falling onto a container. Another in a dangerous condition close to mobile classroom.
St Patrick's Primary School (Crossmaglen)	Fencing and Roof Repairs - Five fencing panels down around school oil tank area and around the nursery area. also tiles off (approx 2 ridge and 6 tiles in total). Remove large branches hanging at front entrance - all staff and pupils not allowed near this area entering school premises another way and parking in chapel park. Two doors hinge issues – wooden nursery boiler room door and the other is the escape door for the mobile classroom Remove fallen tree blocking school entrance. One tree beside the pond is ready to fall - would fall into resident's garden & another uprooted at the back of the nursery - this would fall into the neighbour's lane.
St Patrick's Primary School (Cullyhanna)	12 ft tree down at front car park Replace roof tiles missing in several locations.
St Patrick's Primary School (Dungannon)	Outside lights not working at the front of the school and Car Park area
St Patrick's Primary School (Glenariffe)	Damage to PVC cladding at back of the school
St Patrick's Primary School (Glen)	New porta cabin, felt has come away at a join.
St Patrick's Primary School (Loughgiel)	Timber cladding has come away from a wall of the mobile classroom, exposing the insulation.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Patrick's Primary School (Mayobridge)	Replace section of PVC guttering at Assembly Hall - has completely detached, some of it is damaged.
St Patrick's Primary School (Moneymore)	Repair roof from sand house in outdoor play area - blown off. Replace spouting blown off at shelter outside P6/7 classroom. Electric cables came loose outside kitchen
St Patrick's Primary School (Newry)	Roof tiles and slates loose need repaired/replaced around the school
St Patrick's Primary SMK	External mesh on the extractor fan blown off.
St Paul's High School (Bessbrook)	Metal fence needs repaired due to a fallen tree at back of the school Metal signage to be reattached at the Car Park C area Ball stop has blown down needs reattach at the pitches. 2 Dug out areas have been damaged and need re-paired
St Paul's Primary (Irvinestown)	1 tree from the embankment across the road from the school has fallen down and damaged the metal perimeter fence. 1 maglock not working so the side door of the school was opening
St Paul's Primary (Slievemore)	Replace 1 gate post and re-attach Gate. Replace approx. 2 m long section of 6ft high timber fencing
St Paul's Primary School (Cabra)	External door ripped off
St Peter's Primary School (Moortown)	Tree is uprooted and branches are hanging down onto another tree
St Pius X High School	Roof leaks over Art Dept. and IT Dept. Pitched roof. First floor high level. Roof tiles and ridge tiles blown off during storm.
St Ronan's Primary School (Newry)	Replace various ridge tiles and flat tiles that have come off the roof in 3 different locations on site, water getting through to classroom 10 as a result. Globe cover is not secure, and needs checked at the front of the school.
St Ronan's PS, Lisnaskea	Part of the canopy has blown off at the front of the school
St Ronans Recarson Primary	Electrics P6 mobile classroom damaged from previous storm needs roof repaired/replaced. P1/P2 classes and library also have roofs damaged. Rear elevation of P6 mobile blew off metal tile.
St Scire's Primary	Several roof tiles off 2 pitched roofs. Fascia board also to be repaired/replaced.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
St Teresa's Primary	Roof tiles missing off P1 building.
St Teresa's Primary School (Lurgan)	Aerial has blown down and is hanging at the canteen area - brackets need to be replaced and aerial to be re-secured.
St Teresa's Primary School (Tullyherron)	Replace missing roof slates on main building
St Theresa's Primary (Glebe)	S&F replacement roof slates to various areas of the school, particularly at the front of the school.
St Therese of Lisieux Primary	P2 area - 10 roof tiles off - pitched double storey also at new build area soffit has come away
St Tierney's Primary	Guttering at the after-school's mobile has been blown off during the storm. Fallen tree hit the metal handrail for the steps leading down in the playground and caused it to break leaving the edges jaggy and sharp. All the mesh covering on the new steps was blown off.
St Vincent de Paul Primary	Plaster coming off ceiling in classroom - Skylight leaking in classroom
Steelstown Primary	Follow up with tree surgeon to take down / make safe approx. 3 trees.
Steeple Nursery School	2 plastic sheets have blown off the sandpit roof at the rear of the school.
Stewartstown Primary School	Replace 6 missing roof tiles and lead on the roof. Replace flat roof liner which is missing
Strabane Academy (Derry Road Site)	1 loose roof tile to the front of the school on 2 storey pitched roof.
Strabane Primary	Carry out an appraisal of the M & E installation in the vicinity of the assembly hall and joint roof following storm damage Part of the roof felt has blown off over the assembly hall & also on roof beside assembly hall.
Straidbilly Primary School	Section of mobile classroom cladding has blown off in storm, exposing the structural frame of the mobile.
Straidhavern Primary School	Various fence panels broken and have collapsed - in need of repair.
Strandtown Primary	Some slates have moved on the pavilion building.
Stranmillis Primary	Missing roof slates. Leaks are present at classroom 1 following storm – pitched roof. Also, in a flat roof area at music room leak present in the room.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
Strathearn School	No obvious structural damage to buildings. 1 x Fallen Tree from roots 2 x Badly Damaged trees 1 x Damaged Referee Dugout on Astro Pitch
Sunnylands Primary School	Leak in the ceiling and door frame at P5 classroom, flat roof.
Tamnamore Learning Centre	Replace several ridge tiles at front of main building - have blown off and smashed Replace several tiles on pitched mobile roof above the den - causing a leak Replace wood.
Tandragee Junior High School	Repair damaged fire alarm sounder outside front entrance at mobile 19 - showing fault on fire alarm and will not clear. Tree down, damaged light, cables live. Several trees fallen against EA buses. Also roof repairs required to mobile classroom. Part of the ceiling in room 5 is hanging down, Pitch roof. Can't put children into the classroom.
Tandragee Junior High School MK	2 fan covers have blown off
Tandragee Nursery School	Greenhouse to be removed at the top end of the play area also wooden fence panels to be fitted after greenhouse is removed. Outside canopy to be repaired and painted at the stage area.
Tandragee Primary School	3 trees have come down. 1 is leaning against telephone wire and may take down the pole. Tiles have come off the roof some are ready to come may have asbestos. Ridges tiles off on the old part of the school.
Tandragee Primary School MK	Roof tiles have come loose from storm over door in kitchen , roof tiles missing on pitched roof , flat roof over kitchen is leaking.
Tattygar Primary	Re-felt roof of EA issued storage unit in the playground that has blown off. Approx 4m x 5m.
Taughmonagh Primary	Wooden gate and fence broken at the back of the school
Tempo No 1 Primary SMK	1 double socket in Kitchen's office wont switch on- it has a red trip switch but it won't move
Tempo Primary	Intruder Alarm wont set, it worked after storm but stopped today.
The Irish Society Primary School	Replace damaged Perspex panel on roof of covered area at exit of senior school

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

<b>Property Name</b>	<b>Reported details of damage</b>
The Royal Belfast Academical Institution	<p><b>Inchmarlo</b></p> <ul style="list-style-type: none"> <li>• Buildings inaccessible due to fallen trees within the grounds and on the roads leading to the school. Tree surgeons called to remove fallen trees.</li> <li>• Roof tiles dislodged. Contractor engaged to repair</li> </ul> <p><b>Bladon Park Grounds</b></p> <ul style="list-style-type: none"> <li>• 6 trees down. Tree surgeons removed.</li> <li>• 1 pitch unusable due to hanging branches. Tree surgeon to return to deal with hanging branches</li> </ul> <p><b>Main school</b></p> <ul style="list-style-type: none"> <li>• Fire door blown in and damaged</li> <li>• 2 windows broken</li> </ul>
The Royal School Dungannon	Nothing significant. Loss of a handful of slates and some damage to spouting on the side of one building.
Thornberry Centre	Repair pitched roof of Thornberry Centre portacabin building - several tiles have dislodged; Caretaker has structural concerns.
Thornfield House School	Fallen tree in carpark area and at rear exit. Needs to be cleared from site. Ridge Tile off
Tobermore Primary School	Repair wooden fence/post and gate at the side of the school
Tonagh Primary	Fallen tree damaged perimeter fencing - school access can be accommodated. Wooden Fencing has blown down - approximately 3 panels in the left-hand corner as you look into the playground.
Trench Road Nursery	Pitched tiled roof leak above Nursery 2 and Perspex sheets above canopy/enclosure.
Trinity Nursery	Trees fallen and perimeter fence damaged.
Tullygally Primary School	5 areas where fascia board and soffit is off - 2 outside the hall, 1 outside Nursery 2, 1 side of playground and 1 outside special unit.
Victoria Nursery	Damaged concrete windowsill under the shutter, part of it has come away due to wind / storm Shutter getting repaired. Damage to electric shutter, came off the runners Boundary wall and fencing damaged and leaning into playground area.
Victoria Park Primary School	Green privacy netting at playground as ripped off



**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Victoria Primary School	Replace metal fence panel at front of school PVC roof panels at covered play area - panels broken and off. PVC broken guttering at shelter in playground
Wallace High School	The main roof was ripped in a number of places. School planning for repair Greenhouse damaged with about 9 panes of glass smashed. Neighbour's tree fell and damaged fence
Waringstown Primary School	Significant number of trees down in school ground (one has fallen into a neighbour's garden, caused damage to the school fence, her fence and her garden shed). 1 large portion of Zinc roof/ridge tiles have come off
Wheatfield Primary	1 set of wooden doors ripped of the water tank on the roof - access by ladders (doors still there) 2 metal posts need the cement holes refilled as they are loose - front gate at the entrance
Wheatfield Primary SMK	Roof leaks on dining room roof and replace coving and side panels that have come off in the storm.
Whiteabbey Primary School	2 x roof tiles off at boiler house.
Whitehead Primary School	Roof of water tank on roof of school blown into nature garden (heavy lid for lifting) Repair blocked guttering on outside staffroom causing several leaks inside. Wooden gate at the nursery unit -structure coming away from walls- have it cabled tied at present H&S issue- giving kids free access,
Whitehouse Primary School	1 leak in the Staff Room Tiled Roof of the Nursery Covered walkway has a missing plastic board. Supply & fit new sheet to match missing - ensure safe and secure - prevent further damage.
William Pinkerton Memorial Primary School	Felt is coming off the pitched roof in the Assembly Hall. The brackets that hold it have come off.
Willowbridge Special (Elmbrook)	Various roofs tiles are off above classroom area - high level pitched roof
Windmill Integrated Primary School	<ul style="list-style-type: none"><li>• Top hat of the large outdoor security lighting blew off, narrowly missing a member of staff</li><li>• Covered seating area for parents which was bolted to the cement ground was lifted, blown away and broken in the process. It is irreparable.</li><li>• Letter P from outdoor signage on front wall fell off and broke in 2 pieces</li><li>• Some broken tiles on school roof. Some tiles on internal suspended ceiling were saturated with water and crumbled into classroom</li></ul>
Windsor Hill Primary School	Skylight leaking on pitched roof above main corridor.

**AQW 22401/22-27: Damage to school estates by Storm Éowyn**

Property Name	Reported details of damage
Woodlawn Primary School	No heat in mobile 11 - all fuses checked and all ok - does not believe it was due to storm. Gas Heating. Plastic dome skylight missing in the Playroom 3- toilet area. Felt missing on the roof at the entrance of the Main door 1 No tile missing from Mobile 12.